List of Notices and Directives issued within the Inkomati Water Management Area

No	Activity	Notices	Directives	Feedback to Directive	Case open	Comments	Resolved/ not resolved
			Mbombe	la Local Munic	ipality		
1	For failing to prevent pollution due to pump station overflow at Hillsview	12 April 2013	05 July 2013	25 July 2013	35/07/2014	A follow-up investigation was conducted on the 30 May 2014 at Hillsview Pump station to ascertain whether the pump station was in working condition. During the investigation it was observed that the pump station was not functioning. Case was opened on the 07 July 2014.	Not Resolved
2	For failing to prevent pollution due to pump station overflow in Hazyview next to Telkom technical site.	23 May 2013	-			The pump station was fixed.	Resolved
3	For failing to prevent pollution due to sewage seepage causing white foam on White River.	15 August 2013	-			The broken main sewer pipeline was identified and repaired	Resolved
4	For failing to prevent pollution due to pump station overflow Twin City Hazyview	9 November 2012	18 June 2013	31 October 2013	112/02/2014	Case opened in February 2014. A follow up inspection was conducted on the 16 July 2014. A contractor was busy on site. No overflow. Busy with the construction of silt traps and installing new pumps.	Not Resolved
5	For discharging partially treated wastewater at White River WWTW.	26 September 2013	24 June 2014			A follow-up investigation was conducted on the 14 May 2014 at White River WWTW and it was observed that the WWTW discharges partially treated sewage with foam into the White River. A directive was issued and	Not Resolved

		Ī	<u> </u>			
					epresentations was received still	
					be assessed.	
0 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -	1 March				follow-up investigation was	Not Resolved
manhole overflow at Hillsview 20	014			co	onducted on the 30 May 2014	
approximately 50 meters above the				ar	nd it was observed that there	
Hillsview pump station.				w	as still flow of the sewage into	
				th	ne White River. Follow up to be	
				СС	onducted.	
7 For failing to prevent pollution due to 30	0 June 2014			Aı	n inspection was conducted on	Not Resolved
partially treated wastewater being				th	ne 12 June 2014 and it was	
discharged at Tekwane North WWTW				ol	bserved that the WWTW	
				di	ischarges partially treated	
				se	ewage and there are no	
				m	nonitoring taking place.	
8 For failing to prevent pollution due to 26	6 June 2014			Aı	n inspection was conducted on	Not Resolved
partially treated wastewater being				th	ne 12 June 2014 and it was	
discharged at Rocky's Drift WWTW				ol	bserved that the WWTW	
				di	ischarges partially treated	
				se	ewage into the unnamed stream	
				w	hich is a tributary of Sand River.	
				Re	epresentations was received still	
				to	be assessed.	
		Thaba Chw	eu Local Muni	icipality		
1 For failing to prevent pollution due to 03	3 June 2013	-		Se	ewer line was fixed.	Resolved
broken sewer line to Sabie WWTW.						
2 For failing to prevent pollution due to 19	9 June 2013	-		A	follow-up inspection was	Not Resolved
partially treated wastewater being				cc	onducted on the 13 June 2014	
discharged at Graskop WWTW.				ar	nd it was observed that the	
				se	ewage discharge into the	
				er	mergency dam was not resolve	
			l		incigency dam was not resolve	
1 1					nd the inspection letter will be	
				ar		
				ar dr	nd the inspection letter will be	

						12 August 2014. A directive will be issued.	
3	For failing to prevent pollution due to partially treated wastewater at Sabie WWTW	05 July 2013	31 October 2013	19 March 2013		A follow up investigation was conducted on the 04 April 2014. During the investigation it was observed that electricity has been restored, housekeeping has improved. Another follow-up investigation was conducted on the 17 June 2014, and it was observed that the motor from the clarifier was removed for repairs and the clarifier was covered with sludge. Another inspection was conducted on the 04 July 2014 it was observed that the clarifier was not functioning. Another follow up inspection was conducted on the 17 July 2014 it was observed that the clarifier was functional, but it contained some sludge.	Not resolved
4	For failing to prevent pollution due to sewage TTC manhole overflow in Sabie.	26 July 2013	31 October 2013	31 January 2014	11/05/2014	A follow up investigation was conducted on the 04 April 2014. It was observed that the manhole was still overflowing, raw sewage was flowing into the Klein Sabie River. A Criminal case was opened on the 06 May 2014. Another inspection was conducted on the 04 July 2014 with Captain Mshwane from the SAPS it was observed that the pump station was still overflowing and the	Resolved.

						Municipality has not done anything to fix the manhole. Another follow up inspection was conducted 13 August 2014. It was observed that the manhole was fixed.	
			Bushbuckri	idge Local Mur	nicipality		
1	For failing to prevent pollution due to manhole overflow at Maviljane Township	11 April 2013	24 May 2013			A notice was issued for manhole overflow which the discharges of raw sewage into the Injaka dam. A follow-up inspection was conducted on the 18 April 2013 and a directive dated 24 May 2013 was issued manhole overflow which the discharges of raw sewage into the Injaka dam, another follow-up inspection was conducted on the 27 November 2013 and it was observed that the manhole was fixed.	Resolved
2	For failing to prevent pollution due to partially treated wastewater discharged at Maviljane WWTW	24 May 2013	13 January 2014	14 April 2014	127/08/2014	A notice dated 24 May 2013 was issued for the discharge of partially treated sewage into the Injaka dam. A follow-up inspection was conducted on the 27 November 2013 and a directive dated 13 January 2014 was issued for the discharge of partially treated sewage into the Injaka dam. A follow-up investigation was conducted on the 18 March	Not Resolved

					2014 a courtesy letter dated 14 April 2014 was issued notifying to the Municipality that the IUCMA will proceed to open a criminal case. Criminal case was opened and another follow-up inspection was conducted on the 28 August 2014 with SAPS official and the contractor was onsite.	
3	For failing to prevent pollution due to overflowing septic tanks in Hoxani.	26 September 2013	24 June 2014		An inspection was conducted on the 27 August 2013 and a notice dated was issued to the Municipality for the overflow of septic tank into the environment. A follow-up inspection was conducted on the 06 May 2014 at Hoxani WWTW and it was observed that the gate was lock and the official from BLM did not have the key. The WWTW was not visible due to grass that has overgrown in the WWTW and a directive dated 24 June 2014 was issued.	Not resolved
4	For failing to prevent pollution due to non-functional Thulamahashe WWTW	26 September 2013	09 December 2013	89/02/2014	An inspection was conducted at Thulamahashe WWTW on the 15 August 2013 and it was observed that WWTW discharges partially treated sewage into the Mutlumuvi River and a notice was issued. A follow-up inspection was conducted on the 20 November 2013 and a directive was issued to the Municipality for continuous	Not Resolved

					discharge of partially treated sewage. And another follow-up inspection was conducted on the 15 January 2014 and the situation was not resolved. Following the follow-up inspection a criminal case was opened with Thulamahashe Police Station on the 24 February 2014.
5	For failing to prevent pollution due to partially treated water discharged at Mkhuhlu WWTW	30 September 2013	15 January 2014	06 March 2014	A notice was issued for the discharge of partially treated sewage into the Mapaleni Stream which is a tributary of Sabie River. A follow-up inspection was conducted on the 25 November 2013 and it and a directive was issued for the discharge of partially treated sewage into the Mapaleni Stream which is a tributary of Sabie River. Another follow-up inspection was conducted on the 3 February 2014 and a courtesy letter was issued notifying the Municipality that the IUMCA will proceed to open a criminal case. Representation received on the 30 April 2014 from the BLM stating that they have appointed service provided to fix the pumps and the contract is for the period of 3 months. A follow up inspection will be conducted in July 2014. Another follow-up inspection was

6	For failing to prevent pollution due to manhole overflow and booster pump over flow at section A and C in Thulamahashe	30 September 2013	-		conducted on the 22 August 2014 and it was observed that the pumps are working and the emergency dams is empty and that the contractor will bring TLB to clean the emergency dam. The Pump station and manhole were fixed.	Resolved
7	For failing to prevent pollution at Manghwazi Bio-disc Wastewater Treatment Works	25 October 2013	06 March 2014		A notice was issued. The WWTW was not functional, no inflow, no outflow. A follow-up inspection was conducted on the 3 February 2014 and a directive was issued. Another follow-up inspection was conducted on the 22 August 2014 and the WWTW was not functionally.	Not Resolved
8	For failing to prevent pollution due to damaged sewer line at Bushbuckridge Shopping Complex.	04 December 2013			The sewer line was fixed.	Resolved
9	For failing to prevent pollution due to shopping complex sewage pipeline overflow.	15 January 2014	6 March 2014	24 June 2014	On the 13 June 2014 a follow-up investigation was conducted to ascertain compliance to the directive that was issued and it was observed that the Municipality did not comply with the directive to fix a broken sewer pipeline which discharges raw sewage into the unnamed stream which feeds into the Injaka dam. A courtesy letter was issued notifying the Municipality that the	Resolved

					IUCMA will proceed to open criminal. Follow-up inspection was conducted on the 28 July 2014 and it was observed that the sewer pipeline was fixed.	
10	For failing to prevent pollution due to partially treated wastewater discharged at Tintswalo WWTW	26 June 2014			Inspection was conducted on the 23 May 2014, and it was observed that the WWTW discharges partially treated sewage into the environment with sludge floating and that the humus tank was covered with sludge.	Not Resolved
11	For failing to prevent pollution due to discharge of raw sewage into the environment at Thulamahashe WWTW (Section 20 directive)		25 July 2014		Inspection was conducted at Thulamahashe WWTW on the 16 July 2014 and it was observed that the WWTW was discharging raw sewage into the environment. A follow-up inspection was conducted on the 19 August 2014 and it was observed that the discharge point was closed.	Resolved
			Umjind	i Local Municipality		
1	For failing to prevent pollution due to partially treated wastewater at Umjindi WWTW.	05 July 2013	23 June 2014		A representation was received from the municipality and was accepted by the IUCMA. A follow up inspection was conducted on the 04 December 2013 and the Municipality has failed to adhere with the timeframes as stated in their representation. A courtesy letter dated 04 February 2014 was issued to the Municipality notifying the Municipal Manager that a directive will be issued.	Not Resolved

2	For failing to prevent pollution due to manhole sewage spillage in	-	31 October 2013			Another follow-up inspection was conducted on the 04 June 2014 and during the inspection it was observed that the WWTW was discharging partially treated sewage with sludge floating and a directive was issued. The manhole was unblocked	Resolved
	Barberton.		212		100		
				i Local Munici	pality		
1	For failing to prevent pollution due to neglected Komatipoort WWTW.	24 July 2013	25 October 2013	7 February 2014		Representation was received from the municipality. A follow up inspection conducted on the 02 April 2014. The municipality was busy with refurbishment of the plant. A chlorine house was erected and a security house. There was inflow into the WWTW but there was no discharge. A follow up inspection will be conducted.	Not Resolved
2	For failing to prevent pollution due to partially treated water discharged at Hectorspruit WWTW.	26 September 2013 25 April 2014				A follow-up investigation was conducted on the 02 April 2014 at the WWTW and it was observed that there was no inflow and outflow into the WWTW and another notice was issued. A follow-up inspection was conducted on the 21 August 2014 and it was observed that the chlorine gas was installed and feedback letter will be issued.	Not Resolved

3	For failing to prevent pollution due to partially treated water discharged at Mhlathiplaas WWTW	26 September 2013	30 June 2014	con 201 inve the obse	estigation was conducted on 3 June 2014 and it was served that the ponds were still tered with algae and the ponds	
					re discharging partially treated uent into the Crocodile River. A	
				dire	ective was issued. Follow-up	
					pection was conducted on the	
					June 2014 and a directive was	
				issu		
4	For failing to prevent pollution due to	27	-		Municipality was busy with	Not Resolved
	partially treated water discharged at	September			refurbishment of the plant. A	
	Mhlathikop WWTW	2013			dback letter was sent dated 19	
				Mar	· · · · · · · · · · · · · · · · · · ·	
					pection was conducted on the	
					August 2014 and it was	
					served that the contract has	
					shed refurbishing the WWTW	
					I feedback letter will be issued.	
	T = 6.00	T	1	ni Local Municipality		
1	For failing to prevent pollution due to	03 June 2013	26 June		representation was received	Not Resolved
	partially treated wastewater		2014		m the Municipality. A follow-up	
	discharged at Emthonjeni WWTW.				pection was conducted on the	
					June 2014 and it was observed	
					t the WWTW discharges	
				·	tially treated sewage into the	
					uwspruit and a directive dated	
	For Call and a second state of the	45.4	42.84		June 2014 was issued	Not Decel
2	For failing to prevent pollution due to	15 August	12 March	·	presentation was received from	Not Resolved
	partially treated sewage at Waterval	2013	2014	the	1 / 1	
	Boven WWTW			exte	ension due to the strike. A	

					follow up inspection will be conducted in July 2014. A follow-up inspection was conducted on the 10 July 2014 and it was observed that there were evidence of workings however the contract was not onsite. Reminder letter will be issued notifying the Municipal Manager that the IUCMA will proceed with the opening of criminal case.
			Chief Albert L	uthuli Local Mu	
1	For failing to prevent pollution due to partially treated wastewater discharged at Carolina WWTW.	06 June 2013	09 September 2013		A follow-up investigation was conducted on the 16 June 2014 and it was observed that the WWTW discharges partially treated sewage and a courtesy letter was issued informing the Municipal manager that the IUCMA will proceed with the opening of a criminal case.
2	For failing to prevent pollution due to partially treated water discharged at Ekulindeni sewer pipe line.	10 September 2013	-		The sewage pipeline was repaired Resolved
3	For failing to prevent pollution due to partially treated wastewater discharged at Elukwatini WWTW.	06 March 2014	26 June 2014		A follow-up investigation was conducted on the 4 June 2014 and it was observed that the WWTW discharges partially treated sewage into the Tee River and disinfection of the final effluent is not taking place and a directive dated 26 June 2014 was issued.
			Msukalig	wa Local Munici _l	ipality

1	For failing to prevent pollution due to partially treated wastewater discharged at Breyten Oxidation Ponds	15 January 2014		fr	No representation was received from the Municipality. A follow up inspection will be conducted.	Not Resolved
			Departn	ent of Public Works		
1	For failing to prevent pollution due to partially treated wastewater discharged at Shongwe Hospital WWTW.	25 July 2013	14 January 2014	tl d w P T fc c w d e g tc tı p	Representation was received from the Department of Public Works dated 25 March 2014. A meeting was held with the Department of Public Works, Roads and Transport on the 20 June 2014. A follow up inspection was conducted on the 08 July 2014. It was observed that the plant was discharging partially treated effluent. A verbal directive was given to Public Work officials due to the overflow of partially treated sewage from one of the ponds into the environment and neighboring houses. The verbal directive will be confirmed within 14 working days.	Not Resolved
2	For failing to prevent pollution due to partially treated wastewater discharged at Tonga Hospital WWTW.	28 October 2013 and 06 March 2014		tl a b is fo c a V tı	Representation was received from the Department of public works and the IUCMA rejected it because it did not address the ssues raised in the notice. A follow up inspection was conducted on the 3 June 2014, and it was observed that the NWTW discharges partially treated sewage with floating sludge. A meeting was held with	Not Resolved

3	For failing to prevent pollution due to	24 October	12 March	the Department of Public Works Roads and Transport on the 20 June 2014. A feedback letter wa sent to the Department of Public Works dated 30 June 2014. A follow up inspection wa conducted on the 08 July 2014.and currently waiting for a response from Public Works a per agreement in the meeting tha was conducted. No representation was received	
	partially treated wastewater discharged at Louiville WWTW.	2013	2014	from the Department of Public Works. A follow-up investigation was conducted on the 15 Mar 2014 and it was observed that the WWTW discharges partially treated sewage into the Low's creek. A meeting was held with the Department of Public Works Roads and Transport on the 20 June 2014. A feedback letter was sent to the Department of Public Works dated 25 June 2014. A follow up inspection was conducted on the 08 July 2014 Currently waiting for a response from Public Works as peragreement in the meeting that was conducted.	
4	For failing to prevent pollution due to partially treated wastewater discharged at Lebombo WWTW.	27 September 2013		Representation was received from National Department of Publi Works however it was no sufficient and did not address the	

					issues raised in the notice. The representation will be rejected and a follow up was conducted on the conducted on the 08 August 2014 and a directive will be issued.		
5	For failing to prevent pollution due to partially treated wastewater discharged at Oshoek WWTW.	27 September 2013			Representation was received from National Department of Public Works however it was not sufficient and did not address the issues raised in the notice. The representation will be rejected and a follow up inspection will conducted during the second quarter (July-September 2014) before a directive may be issued		
	Private owned WWTW						
1	Acornhoek Plaza Ponds For failing to prevent pollution due to partially treated wastewater	26 April 2013	26 June 2014		A follow-up investigation was conducted on the 10 June 2014, and it was observed that WWTW discharges raw sewage into the environment and a directive was be issue.		
2	Forever Resorts (Aventura) Badplaas For failing to prevent pollution due to partially treated wastewater	26 September 2013			Representation was received from Forever Resort (Aventura) Badplaas and was accepted by the IUCMA. A follow up inspection was conducted in March 2014. Measures stated in the representation have been implemented. A feedback letter was sent on the 26 June 2014. Forever Resort (Aventura)		

					Badplaas is in the process of	
	Caller /AA'll a Fac Caller Lance and	04.4			applying of a WUL.	Not Developed
3	Caltex/Millys For failing to prevent	01 August			Representation was received from	Not Resolved
	pollution due to partially treated	2013			Caltex/Milly's and was accepted	
	wastewater				by the IUCMA. An action plan has	
					been submitted. A progress report	
					was submitted to the IUCMA	
					dated 10 June 2014.	
4	Sabie River Sun For failing to prevent	31 October	30 June		A follow up was conducted on the	Not Resolved
	pollution due to partially treated	2013	2014		14 May 2014 and it was observed	
	wastewater				that the WWTW discharges	
					partially treated sewage into the	
					Sabie River and the discharge of	
					wastewater from the Hippo pond	
					into the Sabie River and a directive	
					was issued.	
5	Naas Plaza For failing to prevent	26	23 June		No representation was received	Not Resolved
	pollution due to partially treated	September	2014		from Naas Plaza. A follow-up	
	wastewater	2013			investigation was conducted on	
					the 15 May 2014. A directive	
					dated 23 June 2014 was issued.	
				Industries		
1	Safika Oosthuizen Breyten operations	9 September			Meeting was held in October	Not Resolved
	 for the discharge of wastewater 	2013			2013. In a process of applying for	
	into the wetland.				a WULA. A follow-up inspection	
					will be conducted and the	
					directive will follow.	
2	Matumi Golf Estate (please indicate	15 August			For discharging oil from the	Resolved
	here what is issue of concern with	2013			workshop into the unnamed	
	regards to this activity				stream. The discharge was	
					diverted into the septic tank.	
3	Cape Fruit Nelspruit - for the	27			Representation was received.). A	Not Resolved
	discharge of wastewater into the	November			follow up inspection will be	
	environment.	2013			conducted.	

4	Cape Fruits Malelane - For failing to prevent pollution due to partially treated wastewater	31 October 2013			Representation was received from Cape Fruit Malelane and was accepted by the IUCMA. Consultation meeting and follow-up inspection was conducted on the 24 April 2014. Feedback letter was sent dated 26 June 2014.	
5	Delta EMD – traces of previous spillages	30 August 2013			Spillages were cleaned and representation was received.	Resolved
6	York Timber - For failing to prevent pollution due to partially treated wastewater and discharge of wastewater into a wetland.	31 January 2014			Representation was received from York Timber (Sabie Mill). A follow up inspection will be conducted.	Not Resolved
7	Elegant Line Trading (Sawmill) – for discharge of wastewater into the Sabie River.	24 July 2013			No representation was received from Elegent Line Trading (saw Mill). A follow up inspection will be conducted.	Not Resolved
8	Milly's Factory – for disposal of wastewater into a pond.	15 August 2013			Representation was received from milly's Factory however the representation was not fully accepted by the IUCMA because it didn't fully address all issues stated in the Notice. A follow up inspection will be conducted.	
				Mines		
1	Eastside Colliery – collapse of PCD		14 March 2014		Representation was received from Eastside colliery. A follow up investigation was conducted on 11 March 2014. Another follow-up investigation was conducted on the 22 May 2014 and feedback letter date 30 June 2014 was issued to the Mine stating that they did not comply with the	Not resolved

				directive issued and more	
				information was requested from	
				the mine. A follow-up inspection	
				will be conducted on the 18 July	
				2014. Meeting with regarding	
				extension of time to submit all	
				required reports and extension	
				was granted.	
2	Droogvallei Rail Siding – overflow of		14 March	Representation was received from	Not Resolved
	wastewater from the PCD		2014	Droogvallei Rail siding. A follow up	
				investigation was conducted on	
				11 March 2014. Droogvallei Rail	
				Siding requested for extension	
				until 30 April 2014. A follow-up	
				investigation was conducted on	
				the 22 May 2014 and a feedback	
				letter was issued dated 30 June	
				2014A follow-up inspection was	
				conducted on the 18 July 2014. E-	
				mail was received stating that	
				they are still busy with the designs	
				drawing and will be submitted.	
3	Barbrook Mine for tailings spillage		20	Representation was received from	Not Resolved
			September	Barbrook Mine the mine	
			2013	requested for extension of time	
				for conducting the GN704 audit	
				and submission of the report.	
4	TGME Rietfontein wants to start with	15 August		Representation was received from	Not Resolved
	the re-mining operation and license is	2013		TGME Rietfontein and more	
	not issued as yet.			information was requested from	
				TGME. Representations was	
				received still to be assessed.	

5	Elandshoogte Gold Mine to start with	27		Representation was received from	Not Resolved
	the re-mining operation and license is	November		Elandshoogte Gold Mine. To draft	
	not issued as yet.	2013		feedback letter and conduct	
	not issued as yet.	2010		follow-up inspection.	
6	Sheba Gold Mine – discharge of	16 January		Representation was received from	Not Resolved
	wastewater into the river.	2014		Sheba Gold Mine. A follow up	
				inspection will be conducted.	
7	Galaxy Gold Mine -	30	23 June	A follow-up inspection was	Not Resolved
	•	September	2014	conducted on the 13 May 2014.	
		2013		The dam next to the workshop	
				was not lined; there were traces	
				of previous spillages. WWTW was	
				discharging partially treated	
				effluent into the River. A directive	
				has been issued. To conduct a	
				follow-up inspection then we	
				proceed to open a criminal case.	
8	Galaxy Gold Mine – overflow from		19 June	Representation has been received	Not Resolved
	the PCD.		2013	and the monitoring schedule has	
				been reduced.	
9	Pembani Coal Mine, Carolina -		26 June	An inspection was conducted on	Not Resolved
	Overflow of wastewater from the		2014	the 09 June 2014. A directive was	
	Make-up water Dam			issued for the overflow of	
				wastewater from the Make-up	
				Water Dam. Meeting was held on	
				the 25 August 2014 and draft	
				representation was submitted for	
				assessment.	
10.	Pembani Coal Mine -	23 June 2014	21 August	An inspection was conducted on	Not Resolved.
			2014	the 09 June 2014 and it was	
				observed that the mine was using	
				discard material to backfill the	
				Groenvallei pit. There was	
				evidence previous run-off from	

			the pits. A notice was issudirective was issued to tensective the discard material existing coal loading pad.	mporary
11	TGM Elandsdrift Mine	30 June 2014	An inspection was condu the 17 June 2014 and observed that there the op as seized and the Heap Le is under care and maint Representation dated 13 2014 was received still to and give feedback to the re	it was peration ach Pad enance. August perassess